



Fax: (255) 22 2844300, 2844302
PHONE: (255) 22 2198100, 2844291
AFS: HTDQYOYO
E-MAIL: tcaa@tcaa.go.tz, ais@tcaa.go.tz
Website: www.tcaa.go.tz

**UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION
AUTHORITY**
**Aeronautical Information Services
Nyerere/ Kitunda Road Junction
Aviation House, 1st Floor,
P.O. Box 2819, DAR ES SALAAM**

**AIP
Supplement**
05 - 09 and 12/15
08 January 2015

Document No:
TCAA/FRM/ANS/AIS-56

Title: **AIP Supplement**

Page 1 of 1

AERODROMES (AD)

- S05 Kilimanjaro International Airport – HTKJ**
KK 110.9 MHZ ILS RWY 09 not reliable.
(Replace AIP SUP S04/13)
- S06 Kilimanjaro International Airport – HTKJ**
Fuel AVGAS 100LL is not available due to technical problem.
(Replace AIP SUP S05/13)
- S07 Kilimanjaro International Airport – HTKJ**
ILS Monitor at control console is intermittent when runway lights are on.
(Replace AIP SUP S06/13)
- S08 MWANZA International Airport –HTMW**
Taxiway **C** and **D** are operational but caution advised during taxiing due to nil taxiway designators.
(Replace AIP SUP S07/13)
- S09 MWANZA International Airport –HTMW**
Cargo apron is operational but caution advised during parking due to nil marking.
(Replace AIP SUP S08/13)
- S12 Iringa – HTIR**
Fire fighting services are downgraded to NIL due unavailability of fire tender.
(Replace AIP SUP S15/13)