 <p>FAX: (255 22) 2844300, 2844302 PHONE: (255 22) 2198100 AFS: HTDQYOYO Email: tcaa@tcaa.go.tz, ais@tcaa.go.tz Website: www.tcaa.go.tz</p>	<p>UNITED REPUBLIC OF TANZANIA TANZANIA CIVIL AVIATION AUTHORITY Aeronautical Information Services Nyerere /Kitunda Road Junction Aviation House, 1st Floor, P.O. Box 2819, DAR ES SALAAM</p>	<p>AIP Supplement 08/19 01 March 2019</p>
<p>Document No: TCAA/FRM/ANS/AIS-56</p>	<p>Title: AIP Supplement</p>	<p>Page 1 of 5</p>

AERODROME

S08 Abeid Amani Karume International Airport – HTZA


The Airport is undergoing a major construction at a new passenger Terminal II building where part of the work involves a construction of a new Apron for code E Aircraft on the southern side and the existing TWY C.

With effect from 7 May 2018 part of TWY C between intersections of TWY E and C, and TWY F and C had been closed to allow the airside work of connecting the two Aprons and TWY C.


The project is ongoing and is expected to be completed by 31 August 2019. Pilots are advised to strictly adhere to ATC instructions. Additional information and any changes to this AIP Supplement will be notified by NOTAM.

See the affected areas on **Attachment** to this supplement.

(Cancel AIP SUP 11/18)




1921 m



 The Area to be Closed

The open ditch Option 2

KEY
 The Area to be Closed

1921 m

