 <p>FAX: (255 22) 2844300, 2844302  PHONE: (255 22) 2198100  AFS: HTDQYOYO  Email: <a href="mailto:tcaa@tcaa.go.tz">tcaa@tcaa.go.tz</a>, <a href="mailto:ais@tcaa.go.tz">ais@tcaa.go.tz</a>  Website: <a href="http://www.tcaa.go.tz">www.tcaa.go.tz</a></p>	<p><b>UNITED REPUBLIC OF TANZANIA</b>  <b>TANZANIA CIVIL AVIATION AUTHORITY</b>  Aeronautical Information Services  Nyerere /Kitunda Road Junction  Aviation House, 1st Floor,  P.O. Box 2819, DAR ES SALAAM</p>	<p><b>AIP Supplement</b>  11/18  <b>24 May 2018</b></p>
<p><b>Document No:</b>  <b>TCAA/FRM/ANS/AIS-56</b></p>	<p><b>Title: AIP Supplement</b></p>	<p><b>Page 1 of 8</b></p>

## AERODROME

### S11 Abeid Amani Karume International Airport – HTZA

The Airport is undergoing a major construction at a new passenger Terminal II building where part of the work involves a construction of a new Apron for code E Aircraft on the southern side and the existing TWY C.

With effect from 7 May 2018 part of TWY C between intersections of TWY E and C, and TWY F and C is closed to allow the airside work of connecting the two Aprons and TWY C.

The project is ongoing and is expected to be completed by 13 May 2019. Pilots strictly adhere to ATC instructions. Additional information and any changes to this AIP SUP will be announced via NOTAM.

See the affected areas on **Attachment** to this supplement.


**(Cancel NOTAM A0158/18)**



550 m

1921 m

550 m



The Area to be Closed


The open di ch

Option 2

KEY  
The Area to be Closed




1921 m



 The Area to be Closed

The open ditch Option 2

KEY  
 The Area to be Closed



1921 m

