

 <p> <b>FAX:</b> (255 22) 2844300, 2844302  <b>PHONE:</b> (255 22) 2198100  <b>AFS:</b> HTDQYOYO  <b>Email:</b> <a href="mailto:tcaa@tcaa.go.tz">tcaa@tcaa.go.tz</a>, <a href="mailto:ais@tcaa.go.tz">ais@tcaa.go.tz</a>  <b>Website:</b> <a href="http://www.tcaa.go.tz">www.tcaa.go.tz</a> </p>	<p style="text-align: center;"> <b>UNITED REPUBLIC OF TANZANIA</b>  <b>TANZANIA CIVIL AVIATION AUTHORITY</b>  Aeronautical Information Services  Nyerere /Kitunda Road Junction  Aviation House, 1st Floor,  P.O. Box 2819, DAR ES SALAAM </p>	<p style="text-align: center;"> <b>AIP</b>  <b>Supplement</b>  <b>23/16</b>  <b>10 November 2016</b> </p>
<p> <b>Document No:</b>  <b>TCAA/FRM/ANS/AIS-56</b> </p>	<p style="text-align: center;"> <b>Title: AIP Supplement</b> </p>	<p style="text-align: center;"> <b>Page 1 of 1</b> </p>

### AERODROMES (AD)

**S23 BUKOBA – HTBU**

Runway 13/31 Operational but caution advised during Landing/Take-off due to presence of School buildings after the end of Runway 31.

**(Cancel NOTAM C0039/16)**