


| | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|
|  <p> FAX: (255 22) 2844300, 2844302 PHONE: (255 22) 2198100 AFS: HTDQYOYO Email: tcaa@tcaa.go.tz, ais@tcaa.go.tz Website: www.tcaa.go.tz </p> | <p style="text-align: center;"> UNITED REPUBLIC OF TANZANIA TANZANIA CIVIL AVIATION AUTHORITY Aeronautical Information Services Nyerere /Kitunda Road Junction Aviation House, 1st Floor, P.O. Box 2819, DAR ES SALAAM </p> | <p style="text-align: center;"> AIP Supplement 23/16 10 November 2016 </p> |
| <p> Document No: TCAA/FRM/ANS/AIS-56 </p> | <p style="text-align: center;"> Title: AIP Supplement </p> | <p style="text-align: center;"> Page 1 of 1 </p> |

AERODROMES (AD)

S23 BUKOBA – HTBU

Runway 13/31 Operational but caution advised during Landing/Take-off due to presence of School buildings after the end of Runway 31.

(Cancel NOTAM C0039/16)