



Fax: (255) 22 2844300, 2844302  
PHONE: (255) 22 2198100, 2844291  
AFS: HTDQYOYO  
E-MAIL: [tcaa@tcaa.go.tz](mailto:tcaa@tcaa.go.tz), [ais@tcaa.go.tz](mailto:ais@tcaa.go.tz)  
Website: [www.tcaa.go.tz](http://www.tcaa.go.tz)

**UNITED REPUBLIC OF TANZANIA  
TANZANIA CIVIL AVIATION  
AUTHORITY  
Aeronautical Information Services  
Nyerere/ Kitunda Road Junction  
Aviation House, 1st Floor,  
P.O. Box 2819, DAR ES SALAAM**

**AIP  
Supplement  
07 - 09 and 12/15  
08 January 2015**

Document No:  
TCAA/FRM/ANS/AIS-56

Title: **AIP Supplement**

Page 1 of 1

### **AERODROMES (AD)**

- S07 Kilimanjaro International Airport – HTKJ**  
ILS Monitor at control console is intermittent when runway lights are on.  
**(Replace AIP SUP S06/13)**
- S08 MWANZA International Airport –HTMW**  
Taxiway **C** and **D** are operational but caution advised during taxiing due to nil taxiway designators.  
**(Replace AIP SUP S07/13)**
- S09 MWANZA International Airport –HTMW**  
Cargo apron is operational but caution advised during parking due to nil marking.  
**(Replace AIP SUP S08/13)**
- S12 Iringa – HTIR**  
Fire fighting services are downgraded to NIL due unavailability of fire tender.  
**(Replace AIP SUP S15/13)**