



FAX: (255 22) 2844300, 2844302
PHONE: (255 22) 2198100, 2844291.
AFS: HTDQYOYO
Email: tcaa@tcaa.go.tz, ais@tcaa.go.tz
Website: www.tcaa.go.tz

UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION AUTHORITY
Aeronautical Information Services
Nyerere/ Kitunda Road Junction
Aviation House, 1st Floor,
P.O. Box 2819, DAR ES SALAAM

AIP
Supplement
Checklist
01 September 2017

Document No:
TCAA/FRM/ANS/AIS-16

AIP SUPPLEMENT CHECKLIST

Page 1 of 1

The following AIP supplements at the publication of this checklist are still in force; Supplements not included in this list have been cancelled, replaced or incorporated in the AIP.

SUPP NO.	DATE	PART OF THE AIP AFFECTED	LOCATION	SUMMARY OF THE CONTENT
16/17	01 Sept 17	General (GEN)	HTDC	Exchange rate for Aeronautical charges
14/17	20 July 17	Aerodrome(AD)	HTDC	Certificated Aerodromes
08/17	27 Mar 17	Aerodrome(AD)	HTDC	Licensed Aerodromes
03/17	01 Jan 17	Aerodrome(AD)	Mchauru	Lighting systems
02/17	01 Jan 17	Aerodrome(AD)	HTDA	Construction of Terminal Three
23/16	10 Nov 16	Aerodrome(AD)	HTBU	Presence of School Buildings
18/16	24 Aug 16	Aerodrome(AD)	HTKJ	Kilimanjaro Int'l Airport Major Rehabilitation
17/16	18 Aug 16	Aerodrome(AD)	HTNJ	Roughness and potholes on the RWY
16/16	18 Aug 16	Aerodrome(AD)	HTTG	MSA SE SECT has been raised to 1700FT
15/16	18 Aug 16	Aerodrome(AD)	HTTG	Concrete structure has been constructed
09/16	26 May 16	En-route (ENR)	HTDC	Contingency routes for Dar es Salaam FIR
04/16	18 Feb 16	Aerodrome(AD)	HTZA	HTZA RNAV GNSS APCH Procedure RWY 18
18/15	08 Jan 15	Aerodrome(AD)	HTUK	AD Closed
17/15	08 Jan 15	Aerodrome(AD)	HTMS	RWY 18/36 closed
16/15	08 Jan 15	Aerodrome(AD)	HTTU	AD Closed
12/15	08 Jan 15	Aerodrome(AD)	HTIR	Fire Fighting svc downgraded to CAT zero
09/15	08 Jan 15	Aerodrome(AD)	HTMW	Cargo apron not marked
08/15	08 Jan 15	Aerodrome(AD)	HTMW	Taxiway C and D designators not available.
07/15	08 Jan 15	Aerodrome(AD)	HTKJ	ILS Monitor is intermittent
06/15	08 Jan 15	Aerodrome(AD)	HTKJ	Fuel AVGAS 100LL not available
05/15	08 Jan 15	Aerodrome(AD)	HTKJ	KK 110.9 MHz ILS RWY 09 unreliable
04/14	11 Mar 14	Aerodrome(AD)	HTMW	Mwanza GNSS Approach Procedures
02/14	09 Jan 14	Aerodrome(AD)	HTGW	Songwe GNSS Approach Procedures
13/13	17 Apr 13	General (GEN)	HTDC	Tanzania AIS Publications Charges
11/13	20 Feb 13	Aerodrome(AD)	North Mara	New Rock dumping site demarcated
20/10	14 Dec 10	Aerodrome(AD)	HTZA	New Instrument Approach RWY 36
10/09	12 Nov 09	En-route (ENR)	HTDC	VFR flights between HTDA and HTZA
13/07	20 Dec 07	Aerodrome(AD)	HTDC	List of AD owned by TANAPA
15/06	01 Jan 06	Aerodrome(AD)	HTUR	Runway 12/30 Rough surface
05/06	01 Jan 06	Aerodrome(AD)	HTDC	Detailed Surveyed coordinates