



FAX: (255 22) 2844300, 2844302  
 PHONE: (255 22) 2198100, 2844291.  
 AFS: HTDQYOYO  
 Email: [tcaa@tcaa.go.tz](mailto:tcaa@tcaa.go.tz), [ais@tcaa.go.tz](mailto:ais@tcaa.go.tz)  
 Website: [www.tcaa.go.tz](http://www.tcaa.go.tz)

**UNITED REPUBLIC OF TANZANIA**  
**TANZANIA CIVIL AVIATION AUTHORITY**  
 Aeronautical Information Services  
 Nyerere/ Kitunda Road Junction  
 Aviation House, 1st Floor,  
 P.O. Box 2819, DAR ES SALAAM

**AIP**

**Supplement  
 Checklist**

**01 January 2018**

Document No:  
 TCAA/FRM/ANS/AIS-16

AIP SUPPLEMENT CHECKLIST

Page 1 of 1

**The following AIP supplements at the publication of this checklist are still in force; Supplements not included in this list have been cancelled, replaced or incorporated in the AIP.**

| SUPP NO. | DATE       | PART OF THE AIP AFFECTED | LOCATION   | SUMMARY OF THE CONTENT                         |
|----------|------------|--------------------------|------------|--|
| 01/18    | 01 Jan 18  | General (GEN)            | HTDC       | Exchange rate for Aeronautical charges         |
| 20/17    | 27 Mar 17  | Aerodrome(AD)            | HTDC       | Licensed Aerodromes                            |
| 17/17    | 28 Sept 17 | En-route (ENR)           | HTDC       | VFR Operating Procedures within DAR TMA        |
| 14/17    | 20 July 17 | Aerodrome(AD)            | HTDC       | Certificated Aerodromes                        |
| 03/17    | 01 Jan 17  | Aerodrome(AD)            | Mchauru    | Lighting systems                               |
| 02/17    | 01 Jan 17  | Aerodrome(AD)            | HTDA       | Construction of Terminal Three                 |
| 23/16    | 10 Nov 16  | Aerodrome(AD)            | HTBU       | Presence of School Buildings                   |
| 18/16    | 24 Aug 16  | Aerodrome(AD)            | HTKJ       | Kilimanjaro Int'l Airport Major Rehabilitation |
| 16/16    | 18 Aug 16  | Aerodrome(AD)            | HTTG       | MSA SE SECT has been raised to 1700FT          |
| 15/16    | 18 Aug 16  | Aerodrome(AD)            | HTTG       | Concrete structure has been constructed        |
| 09/16    | 26 May 16  | En-route (ENR)           | HTDC       | Contingency routes for Dar es Salaam FIR       |
| 04/16    | 18 Feb 16  | Aerodrome(AD)            | HTZA       | HTZA RNAV GNSS APCH Procedure RWY 18           |
| 18/15    | 08 Jan 15  | Aerodrome(AD)            | HTUK       | AD Closed                                      |
| 17/15    | 08 Jan 15  | Aerodrome(AD)            | HTMS       | RWY 18/36 closed                               |
| 16/15    | 08 Jan 15  | Aerodrome(AD)            | HTTU       | AD Closed                                      |
| 12/15    | 08 Jan 15  | Aerodrome(AD)            | HTIR       | Fire Fighting svc downgraded to CAT zero       |
| 09/15    | 08 Jan 15  | Aerodrome(AD)            | HTMW       | Cargo apron not marked                         |
| 08/15    | 08 Jan 15  | Aerodrome(AD)            | HTMW       | Taxiway C and D designators not available.     |
| 07/15    | 08 Jan 15  | Aerodrome(AD)            | HTKJ       | ILS Monitor is intermittent                    |
| 06/15    | 08 Jan 15  | Aerodrome(AD)            | HTKJ       | Fuel AVGAS 100LL not available                 |
| 04/14    | 11 Mar 14  | Aerodrome(AD)            | HTMW       | Mwanza GNSS Approach Procedures                |
| 02/14    | 09 Jan 14  | Aerodrome(AD)            | HTGW       | Songwe GNSS Approach Procedures                |
| 13/13    | 17 Apr 13  | General (GEN)            | HTDC       | Tanzania AIS Publications Charges              |
| 11/13    | 20 Feb 13  | Aerodrome(AD)            | North Mara | New Rock dumping site demarcated               |
| 20/10    | 14 Dec 10  | Aerodrome(AD)            | HTZA       | New Instrument Approach RWY 36                 |
| 10/09    | 12 Nov 09  | En-route (ENR)           | HTDC       | VFR flights between HTDA and HTZA              |
| 13/07    | 20 Dec 07  | Aerodrome(AD)            | HTDC       | List of AD owned by TANAPA                     |
| 15/06    | 01 Jan 06  | Aerodrome(AD)            | HTUR       | Runway 12/30 Rough surface                     |
| 05/06    | 01 Jan 06  | Aerodrome(AD)            | HTDC       | Detailed Surveyed coordinates                  |