



TEL: 255 22 2110223/224
 FAX: 255 22 2110264
 AFTN: HTDAYNYX
 E-mail: tcaa.dia@tcaa.go.tz
nofdia@tcaa.go.tz
 Website: www.tcaa.go.tz

UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION AUTHORITY
 Aeronautical Information Management
 International NOTAM Office
 P. O. Box 18001,
 DAR ES SALAAM
 TANZANIA

MONTHLY NOTAM

LIST

Series A

01 JUNE 2017

Document No:
TCAA/FRM/ANS/AIM-32

Title: Monthly List of Valid NOTAM

Page 1 of 4

THE FOLLOWING NOTAM SERIES A WERE STILL VALID ON 01 JUNE 2017 NOTAM NOT INCLUDED HAVE BEEN CANCELLED, TIME EXPIRED, SUPERSEDED BY AIP SUPPLEMENT OR INCORPORATED IN THE AIP.

SERIES: A	2017: 0162 0161, 0153, 0152, 0151, 0150, 0149, 0142, 0135, 0134, 0132, 0113, 0083, 0082, 0068, 0067, 0066, 0064, 0060, 0055, 0054, 0049, 0048, 0047 AND 0046 2016: 0316
A0162/17	170601 DAR ES SALAAM FIR HTDC 1706010000/1706302359 EST NOTAM CHECKLIST
A0161/17	170531 ARUSHA HTAR 1706010330/1708311530 EST AR 391KHZ NDB COMPLETELY WITHDRAWN. (REF: AIP HTAR AD 2.19)
A0153/17	170526 SONGWE HTGW 1705260800/ PERM SW 340KHZ NDB COMPLETELY WITHDRAWN. (REF: AIP HTGW AD 2.19)
A0152/17	170525 DAR ES SALAAM FIR HTDC 1705250955/1706221530 NIL AIRAC PUBLICATION EFFECTIVE DATE 22 JUN 2017. (REF: AIP GEN 3.1- 4).
A0151/17	170523 ABEID AMANI KARUME INTL AIRPORT HTZA 1705231500/1706221530 EST ZZ FREQ. 385 KHZ NDB U/S DUE MAINT.
A0150/17	170523 DAR ES SALAAM FIR HTDC 1705230600/1706211300 DLY 0600-1300 MIL BOMBS DESTRUCTIONS EXER WILL TAKE PLACE AT KASAMWA (GEITA DISTRICT) WI AN AREA ENCLOSED WITH THE FLW COORD:- 0247S 3216E 0247S 3224E

This is a controlled Document

	0252S 3216E 0252S 3224E PILOTS TO AVOID THE AREA AND STRICTLY ADHERE TO ATC INSTRUCTIONS. FM GND TO 10000FT.
A0149/17	170522 DAR ES SALAAM FIR HTDC 1705220931/1706211530 EST NYANSHANA RELAY STN FREQ 119.3MHZ OPR BUT WEAK.
A0142/17	170518 MWANZA HTMW 1705180430/1708171630 EST DLY 0430-1630 RWY 12/30 OPR BUT CTN ADVISED DUE CONST OF CARGO TWY WIP WITHIN THE STRIP AT THE THR OF RWY 12 (NORTH/WEST SIDE). PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.
A0135/17	170511 JULIUS NYERERE INTL AIRPORT HTDA 1705150330/1708141330 EST PORTION OF TWY 'P' FM GATE 'E' TO INT OF RWY 23 CLSD DUE WIP, PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.
A0134/17	170511 JULIUS NYERERE INTL AIRPORT HTDA 1705150330/1708141330 EST GATE 'E' CLSD DUE WIP, PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.
A0132/17	170510 DAR ES SALAAM FIR HTDC 1705100806/1708101530 EST PSR U/S.
A0083/17	170404 MWANZA HTMW 1704040952/1707041530 EST RWY END LGT RWY 12 TEMPO SHIFTED BY 30M INWARD FM THE BEGINNING OF RWY 30 DUE WIP. (REF: AIP HTMW AD 2.14).
A0082/17	170404 MWANZA HTMW 1704040851/1707041530 EST THR RWY 30 DISPLACED BY 300M DUE WIP DECLARED DIST TO READ AS FLW.: RWY TORA TODA ASDA LDA 12 3270M 3270M 3270M 3108M 30 3270M 3270M 3270M 3000M (REF: AIP HTMW AD 2.13).
A0068/17	170324 ABEID AMANI KARUME INTL AIRPORT HTZA 1703240634/ PERM ADDN RWY PHYSICAL CHARACTERISTICS AS FLW:- RWY RESA 18 240x90 36 240x90 (REF:AIP HTZA AD 2.12)
A0067/17	170324 KILIMANJARO INTL AIRPORT HTKJ 1703240628/ PERM SOME RWY PHYSICAL CHARACTERISTICS HAVE CHANGED AS FLW:- RWY CWY RESA 09 300x150 240x90 27 300x150 240x90 (REF:AIP HTKJ AD 2.12)

A0066/17	<p>170324 JULIUS NYERERE INTL AIRPORT HTDA 1703240617/PERM SOME RWY PHYSICAL CHARACTERISTICS HAVE CHANGED AS FLW:-</p> <table border="1"> <thead> <tr> <th>RWY</th> <th>SLOPE</th> <th>CWY</th> <th>RESA</th> </tr> </thead> <tbody> <tr> <td>05</td> <td>-1.2%</td> <td>300x300</td> <td>UNGRADED</td> </tr> <tr> <td>23</td> <td>+1.2%</td> <td>300x300</td> <td>240x300</td> </tr> <tr> <td>14</td> <td>-0.4%</td> <td>300x213</td> <td>240x200</td> </tr> <tr> <td>32</td> <td>+0.4%</td> <td>300x213</td> <td>240x200</td> </tr> </tbody> </table> <p>(REF:AIP HTDA AD 2.12)</p>	RWY	SLOPE	CWY	RESA	05	-1.2%	300x300	UNGRADED	23	+1.2%	300x300	240x300	14	-0.4%	300x213	240x200	32	+0.4%	300x213	240x200
RWY	SLOPE	CWY	RESA																		
05	-1.2%	300x300	UNGRADED																		
23	+1.2%	300x300	240x300																		
14	-0.4%	300x213	240x200																		
32	+0.4%	300x213	240x200																		
A0064/17	<p>170323 KILIMANJARO INTL AIRPORT HTKJ 1703231230/PERM DECLARED DISTANCES HAVE CHANGED AS FLW:-</p> <table border="1"> <thead> <tr> <th>RWY</th> <th>TORA</th> <th>TODA</th> <th>ASDA</th> <th>LDA</th> </tr> </thead> <tbody> <tr> <td>09</td> <td>3600</td> <td>3900</td> <td>3660</td> <td>3600</td> </tr> <tr> <td>27</td> <td>3600</td> <td>3900</td> <td>3660</td> <td>3600</td> </tr> </tbody> </table> <p>(REF:AIP HTKJ AD 2.13)</p>	RWY	TORA	TODA	ASDA	LDA	09	3600	3900	3660	3600	27	3600	3900	3660	3600					
RWY	TORA	TODA	ASDA	LDA																	
09	3600	3900	3660	3600																	
27	3600	3900	3660	3600																	
A0060/17	<p>170321 JULIUS NYERERE INTL AIRPORT HTDA 1703210712/PERM DUE TO APN LAYOUT CHANGES FM ORIGINAL APN LAYOUT ON AEROBRIDGES D1, D2, E1, E2 AND E3, PILOTS ADVISED TO FLW MARSHALLER'S INSTRUCTIONS.</p>																				
A0055/17	<p>170315 JULIUS NYERERE INTL AIRPORT HTDA 1703151051/1706131530 EST AWOS (AUTOMATIC WEATHER OBSERVING SYSTEM) U/S.</p>																				
A0054/17	<p>170314 MWANZA HTMW 1703140605/1706141500 EST APCH LGT RWY 30 REMOVED DUE EXCAVATION AND BACKFILLING WIP ON THE EXTENDED PART OF RWY 30.</p>																				
A0049/17	<p>170304 DAR ES SALAM FIR HTDC 1703040500/1706051300 EST DLY 0500-1300 DANGER AREA HTD9, HTD10 AND HTD11 ACTIVATED (REF AIP ENR 5.1-3) FM GND TO 20000FT.</p>																				
A0048/17	<p>170304 DAR ES SALAAM FIR HTDC 1703040500/1706051300 EST DLY 0500-1300 MIL TRAINING FLT WILL TAKE PLACE FM HTMW COORD 022638S 0325554E TO THE AREA HTD9, HTD10, HTD11 AND BACK TO HTMW, PILOTS TO EXP DLA AND STRICTLY ADHERE TO ATC INSTRUCTIONS, FM GND TO 10000FT.</p>																				
A0047/17	<p>170304 DAR ES SALAAM FIR HTDC 1703040400/1706051300 EST DLY 0400 – 1300 MIL TRAINING FLT WILL TAKE PLACE FM TANGA WI AN AREA ENCLOSED WITH THE FOLLOWING COORD:- 05 02 24.705S 038 59 05.881E 04 56 35.986S 038 48 33.782E 05 22 27.105S 038 58 33.955E 05 11 02.295S 039 02 26.620E, PILOTS TO AVOID THE AREA AND STRICTLY ADHERE TO ATC INSTRUCTIONS. CIVILIAN OPS</p>																				

	AT HTTG COMMENCE AT NML TIME 0430 UTC, FM GND TO 6000FT.
A0046/17	170304 DAR ES SALAAM FIR HTDC 1703040500/1706051300 EST MON – FRI 0500 – 1300 MIL TRAINING FLT WILL TAKE PLACE FM HTDA COORD 065241S 0391209E TO HTNG COORD 0643S 03808E AND BACK TO HTDA, PILOTS TO EXP DLA AND STRICTLY ADHERE TO ATC INSTRUCTIONS, FM 1500FT TO 7000FT.
A0316/16	161230 JULIUS NYERERE INTL AIRPORT HTDA 1612301623/PERM PRKG PSN E3, E2-A, E2-B, D1-A, AND D1-B OPR WITH ACFT VISUAL DOCKING GUIDANCE SYSTEM.
	LATEST PUBLICATIONS: AIP AMENDMENT NR 0059/17 AIP SUPPLEMENT NR 0012/17 AIC NR 0011/17 CHECKLIST OF VALID AICS: YEAR 2000: 3 6 7 8 9 10 11 12 13 14 15 16 17 18 20 21 28 29 30 31 33 35 36 37 40 41 43 46 47 51 53 55 AND 56 2001: 3 2002: 2 AND 4 2003: 3 7 8 13 AND 14 2004: 5 AND 8 2005: 4 AND 12 2006: 8 9 AND 10 2007: 8 2008: 3 6 8 AND 10 2009: 4 7 8 10 12 13 AND 14 2010: 3 AND 4 2011: 3 4 AND 5 2012: 10 AND 11 2013: 3 7 AND 9 2014: 3 4 5 AND 10 2015: 3 5 AND 7 2017: 1 2 3 4 5 6 8 9 10 AND 11 CHECKLIST OF VALID AIP SUPPLEMENTS: YEAR 2006: 5 AND 15 2007: 13 2009: 10 2010: 20 2013: 11 AND 13 2014: 2 AND 4 2015: 5 6 7 8 9 12 16 17 18 AND 32 2016: 4 9 15 16 17 18 AND 23 2017: 2 3 5 8 9 AND 12
	***** END *****