

 <p>FAX: (255 22) 2844300, 2844302 PHONE: (255 22) 2198100, 2844291. AFS: HTDQYOYO Email: tcaa@tcaa.go.tz, ais@tcaa.go.tz Website: www.tcaa.go.tz</p>	<p>UNITED REPUBLIC OF TANZANIA TANZANIA CIVIL AVIATION AUTHORITY Aeronautical Information Services Nyerere/ Kitunda Road Junction Aviation House, 1st Floor, P.O. Box 2819, DAR ES SALAAM</p>	<p>AIP Supplement Checklist</p> <p>11 January 2019</p>
<p>Document No: TCAA/FRM/ANS/AIS - 16</p>	<p>AIP Supplements checklist</p>	<p>Page 1 of 1</p>

The following AIP supplements at the publication of this checklist are still in force; Supplements not included in this list have been cancelled, replaced or incorporated in the AIP.

SUPP NO.	DATE	PART OF THE AIP AFFECTED	LOCATION	SUMMARY OF THE CONTENT
05/19	11 Jan 19	En-route (ENR)	HTDC	Contingency routes for Dar es Salaam FIR
04/19	10 Jan 19	Aerodrome (AD)	HTMT	RWY Extension and Rehabilitation WIP
03/19	03 Jan 19	General (GEN)	HTDC	Tanzania AIM Publications Charges
01/19	01 Jan 19	General (GEN)	HTDC	Exchange rate for Aeronautical charges
23/18	28 Nov 18	Aerodrome (AD)	HTDC	Certificated Aerodromes
22/18	28 Nov 18	Aerodrome (AD)	HTDC	Licensed Aerodromes
11/18	24 May 18	Aerodrome (AD)	HTZA	Construction of new Apron for code E Aircraft
09/18	24 May 18	Aerodrome (AD)	HTDA	Construction of Terminal Three
17/17	28 Sep 17	En-route (ENR)	HTDC	VFR Operating Procedures within DAR TMA
03/17	01 Jan 17	Aerodrome (AD)	Mchauru	Lighting systems
16/16	18 Aug 16	Aerodrome (AD)	HTTG	MSA SE SECT has been raised to 1700FT
15/16	18 Aug 16	Aerodrome (AD)	HTTG	Concrete structure has been constructed
04/16	18 Feb 16	Aerodrome (AD)	HTZA	HTZA RNAV GNSS APCH Procedure RWY 18
18/15	08 Jan 15	Aerodrome (AD)	HTUK	AD Closed
17/15	08 Jan 15	Aerodrome (AD)	HTMS	RWY 18/36 closed
16/15	08 Jan 15	Aerodrome (AD)	HTTU	AD Closed
12/15	08 Jan 15	Aerodrome (AD)	HTIR	Fire Fighting svc downgraded to CAT zero
09/15	08 Jan 15	Aerodrome (AD)	HTMW	Cargo apron not marked
08/15	08 Jan 15	Aerodrome (AD)	HTMW	Taxiway C and D designators not available.
07/15	08 Jan 15	Aerodrome (AD)	HTKJ	ILS Monitor is intermittent
04/14	11 Mar 14	Aerodrome (AD)	HTMW	Mwanza GNSS Approach Procedures
02/14	09 Jan 14	Aerodrome (AD)	HTGW	Songwe GNSS Approach Procedures
11/13	20 Feb 13	Aerodrome (AD)	North Mara	New Rock dumping site demarcated
20/10	14 Dec 10	Aerodrome (AD)	HTZA	New Instrument Approach RWY 36
13/07	20 Dec 07	Aerodrome (AD)	HTDC	List of AD owned by TANAPA
15/06	01 Jan 06	Aerodrome (AD)	HTUR	Runway 12/30 Rough surface