



**UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION AUTHORITY
Aeronautical Information Services**

AERONAUTICAL INFORMATION CIRCULAR

P.O. Box 2819 DAR ES SALAAM.
FAX: 255-22-2118905
PHONE: 255- 22- 2115079/80, 2111951
COMM: DIRAIR
AFTN: HTDQYOYO
Email: tcaa@tcaa.go.tz
Website: <http://www.tcaa.go.tz>

<p>AIC 6/2000 (Pink 2) 27 January 2000</p>

TCAA/T.20/97

The following circular is promulgated for information, guidance and necessary action.

M. Munyagi
Director General

SSR CODE FOR ALL FLIGHTS

Pilots of aircraft operating or entering the Dar es Salaam FIR, who have not received specific instructions from Air Traffic Control concerning the setting of the transponder, shall operate transponder on mode A and C code 2000 when operating in the FIR and maintain that code setting until otherwise instructed.

Pilots of VFR flights in the Dar es Salaam FIR shall activate their transponders on mode A and C and select code 2000, unless otherwise instructed.

Activation of the transponder enables IFR aircraft of TCAS equipped aircraft to receive position and altitude information through their on board TCAS/Navigation display. This information prevents hazardous situation in flight.

** *** **