



**UNITED REPUBLIC OF TANZANIA**  
**TANZANIA CIVIL AVIATION AUTHORITY**  
Aeronautical Information Services

**AERONAUTICAL INFORMATION CIRCULAR**

P.O. Box 2819 DAR ES SALAAM.  
FAX: 255-22-2118905  
PHONE: 255-22-2115078/79/80, **2111951**.  
COMM: DIRAIR  
AFTN: HTDQYOYO  
Email: [tcaa@tcaa.go.tz](mailto:tcaa@tcaa.go.tz)  
Website: <http://www.tcaa.go.tz>

**AIC**  
**47/2000**  
(Pink 25)  
**7 September 2000**

---

*The following circular is hereby promulgated for information, guidance and necessary action*

*M. Munyagi*  
Director General

---

**INFRINGEMENT OF PROHIBITED / RESTRICTED  
AREAS NGERENGERE (HTP6 AND HTR7)**

The Ngerengere restricted and prohibited areas are located to the west of Dar-es-Salaam Airport and their dimensions are published in the AIP Tanzania pages ENR 5.1-2.

Of late there has been a number of incidents of aircraft infringing into these areas without permission from the designated authority. Such action can imperil the safety of aircraft and its occupants. Pilots /aircraft operators are required to familiarize themselves with these restrictions and pilots must keep clear of these areas at all times.

Failure to do so will lead to stern action being taken against the pilot and the aircraft operator, culminating in the suspension/revocation of the pilots license and legal proceeding being instituted against the operator.

***Cancel AIC 5/1993***