 <p>FAX: (255 22) 2844300, 2844302  PHONE: (255 22) 2198100  AFS: HTDQYOYO  Email: <a href="mailto:tcaa@tcaa.go.tz">tcaa@tcaa.go.tz</a>,  <a href="mailto:ais@tcaa.go.tz">ais@tcaa.go.tz</a>  Website: <a href="http://www.tcaa.go.tz">www.tcaa.go.tz</a></p>	<p><b>UNITED REPUBLIC OF TANZANIA</b>  TANZANIA CIVIL AVIATION AUTHORITY  Aeronautical Information Management  Nyerere/ Kitunda Road Junction  Aviation House, 1st Floor, P.O. Box 2819,  DAR ES SALAAM</p>	<p><b>AIP</b>  <b>Supplement</b>  <b>04/26</b>  <b>Published on</b>  <b>14 January 2026</b></p>
<p><b>Document No:</b>  <b>TCAA/FRM/ANS/AIM - 56</b></p>	<p><b>Title: AIP Supplement</b></p>	<p><b>Page 1 of 2</b></p>

## AERODROMES (AD)

### S04 Musoma Airport – HTMU

Musoma Airport is undergoing major rehabilitation and upgrading. The work commenced on 22<sup>nd</sup> October 2021 and is expected to be completed on 30<sup>th</sup> June 2026. The rehabilitation and upgrading will involves;

A: Upgrading works on the portion of Runway 18/36 in progress, first 923M from Threshold of Runway 36 temporarily closed from 14<sup>th</sup> January 2026 to 30<sup>th</sup> June 2026.

**Declared Distances Available to read as follows: -**

<i>RWY Designator</i>	<i>TORA (M)</i>	<i>TODA (M)</i>	<i>ASDA (M)</i>	<i>LDA (M)</i>
1	2	3	4	5
18	900	900	900	900
36	900	900	900	900


B: Reconstruction of the existing Runway (RWY 18/36) from 1600M to 1705M in length and 30M wide including associated Taxiways and Apron.

**(Cancel AIP SUP 37/25)**

**See Attachment to this AIP Supplement**

ATTACHMENT TO AIP SUP 04/26

MUSOMA RUNWAY REHABILITATION



TANZANIA CIVIL AVIATION AUTHORITY

14 January 2025