



FAX: (255 22) 2844300, 2844302
 PHONE: (255 22) 2198100
 AFS: HTDQYOYO
 Email: tcaa@tcaa.go.tz,
ais@tcaa.go.tz
 Website: www.tcaa.go.tz

UNITED REPUBLIC OF TANZANIA
 TANZANIA CIVIL AVIATION AUTHORITY
 Aeronautical Information Management
 Nyerere/ Kitunda Road Junction
 Aviation House, 1st Floor,
 P.O. Box 2819, DAR ES SALAAM

AIP
 Supplement
 03/26
 Published on
 02 JAN 2026

Document No:
 TCAA/FRM/ANS/AIM - 56

Title: AIP Supplement

Page 1 of 2

AERODROMES (AD)

S03 Mtemere Airport – HTTE

Mtemere Airport major rehabilitation commenced on 10 August 2023 and expected to be completed on 30 March 2026.

The rehabilitation and upgrading involves

- I. Extension of Runway (RWY 09/27) from 1270M to 1800M length and 30M wide
- II. Apron 24840 meters square
- III. Taxiway 600M length 23M wide
- IV. Installation of Visual Aids
- V. Pavement Surface of gravel polymer Stabilized with PCN 12/F/C/Y/T
- VI. Terminal Building
- VII. Aerodrome control tower building for establishment of Air Navigation Services.

The existing Runway will be available for aircraft operations during rehabilitation

Declared Distances Available


RWY Designator	TORA (M)	TODA (M)	ASDA (M)	LDA (M)
1	2	3	4	5
09	1270	1270	1270	1270
27	1270	1270	1270	1270

(Cancel AIP SUP 40/25)

See Attachments to this AIP Supplement

ATTACHMENT TO AIP SUP 03/26

MTEMERE RUNWAY REHABILITATION



TANZANIA CIVIL AVIATION AUTHORITY

02 January 2026