

 FAX: (255 22) 2844300, 2844302 PHONE: (255 22) 2198100 AFS: HTDQYOYO Email: tcaa@tcaa.go.tz, ais@tcaa.go.tz Website: www.tcaa.go.tz	UNITED REPUBLIC OF TANZANIA TANZANIA CIVIL AVIATION AUTHORITY Aeronautical Information Management Nyerere/ Kitunda Road Junction Aviation House, 1st Floor, P.O. Box 2819, DAR ES SALAAM	AIP Supplement 40/25 Published on 08 DEC 2025
Document No: TCAA/FRM/ANS/AIM - 56	Title: AIP Supplement	Page 1 of 2

AERODROMES (AD)

S40 Mtemere Airport – HTTE

Mtemere Airport major rehabilitation commenced on 10 August 2023 and expected to be completed on 30 December 2025.

The rehabilitation and upgrading involves

- I. Extension of Runway (RWY 09/27) from 1270M to 1800M length and 30M wide
- II. Apron 24840 meters square
- III. Taxiway 600M length 23M wide
- IV. Installation of Visual Aids
- V. Pavement Surface of gravel polymer Stabilized with PCN 12/F/C/Y/T
- VI. Terminal Bulding
- VII. Aerodrome control tower building for establishment of Air Navigation Services.

The existing Runway will be available for aircraft operations during rehabilitation

Declared Distances Available


<i>RWY Designator</i>	<i>TORA (M)</i>	<i>TODA (M)</i>	<i>ASDA (M)</i>	<i>LDA (M)</i>
1	2	3	4	5
09	1270	1270	1270	1270
27	1270	1270	1270	1270

(Cancel AIP SUP 15/25)

See Attachments to this AIP Supplement

ATTACHMENT TO AIP SUP 40/25

MTEMERE RUNWAY REHABILITATION



TANZANIA CIVIL AVIATION AUTHORITY

08 December 2025